

Designing, manufacturing and deploying  
1000 custom devices.  
What can go wrong?


Mateusz Banaszek

16th November 2019


## The device – outside




# The device – inside




# The device – 1000 times




# The device – network




# Running an experiment



# Running an experiment




# Running an experiment







# Running an experiment




# Running an experiment




# Running an experiment




# Running an experiment




# Running an experiment



# Running an experiment





# Running an experiment



What can go wrong?



# What can go wrong?



designing, manufacturing, deploying

1000 devices

Expect unexpected

Expect unexpected

Thank you!